

TECHNICAL BULLETIN

Incorrect installation of the most popular GM and Ford release bearings (N083SA, N1714SA, N1716, N1716SA) is a leading cause of warranty claims. Before installing your newly purchased clutch kit, please note the following illustrations and the correct installation of the retaining clips to the release bearing. The retaining clip **MUST BE** on the inside (figure 2) of the release bearing to avoid damage and nullifying any warranty.

Figure 1



Retaining clip on the outside of bearing

Figure 2



Retaining clip on the inside of bearing

WARNING: *Any warranty will not be honored on any associated parts if the release bearing shows any evidence of marks, gouges or notching on the release bearing collar from the fork retaining clips not being installed correctly under the release bearing collar.*