



Technical Service Bulletin

In 1990 1.9L Ford Escort applications, the release bearing cross shaft is supported by plastic bushings in the transaxle.

Bushing wear can cause a binding cross shaft and hard pedal, resulting in flexing and cracking of the firewall in the area of the cable.

Affected Applications:

1990 Ford Escort 1.9L 116"



- * Check the release system and all attachment points for damage.***
- * Always replace the bushings.***