



## Technical Service Bulletin

A “growling” noise may be heard when the clutch is either released or engaged at higher engine speeds. The noise is caused by vibration at the connection between the release fork and cable.

Install an isolator dampener, Ford part # F4ZZ-7C530-A, at the fork-to-cable junction to eliminate the noise.



***Clutch Cable CC318***

### **Affected Applications:**

Year	Make	Model	Engine
1994	Ford	Mustang	5.0L

***\*For additional information, refer to Ford bulletin #94-20-7***