



## Technical Service Bulletin

### Hard Pedal Concerns

1985-1994 Chevrolet/GMC C/K, G, R and S/T Series, Blazer, Jimmy, Sonoma Hard pedal and scraping noise while actuating the clutch pedal may be caused by failure of the clutch pedal return spring.



*GM Clutch Pedal Return Spring*

Remove the return spring. It is not needed for proper operation.

#### **Affected Applications:**

Year	Make	Engine
1985-1993	Chevrolet	4 Cyl 2.5L 151"
1985-1993	Chevrolet	4 Cyl 2.8L 171"
1989-1994	Chevrolet	6 Cyl 4.3L 262"
1988-1994	Chevrolet	8 Cyl 5.0L 305"
1988-1994	Chevrolet	8 Cyl 5.7L 350"
1990-1993	Chevrolet	8 Cyl 6.2L 381"
1985-1993	GMC	4 Cyl 2.5L 151"
1985-1993	GMC	4 Cyl 2.8L 171"
1989-1994	GMC	6 Cyl 4.3L 262"
1988-1994	GMC	8 Cyl 5.0L 305"
1988-1994	GMC	8 Cyl 5.7L 350"
1990-1993	GMC	8 Cyl 6.2L 381"

*\*For additional information, refer to GM bulletin #46-73-03.*