



Technical Service Bulletin

Replace Slave Cylinder to Eliminate Hard Pedal/Release Problems

In 1993-98 Ford Bronco, Explorer, F-Series, Ranger; Mazda B2300, B3000, B4000, Navajo applications, hard pedal/release problems may result from leaks in the internal seal of the slave cylinder.



Replace the slave cylinder with one that contains an upgraded seal to prevent leakage.

Affected Applications:

Year	Make	Engine	
1997-1997	Ford	Bronco, F Series	6 Cyl 4.2L 256"
1993-1998	Ford	Bronco, F Series	6 Cyl 4.9L 300"
1993-1998	Ford	Bronco, F Series	8 Cyl 5.8L 351"
1993-1998	Ford	Bronco, F Series	8 Cyl 5.0L 302"
1993-1998	Ford	Bronco, F Series	8 Cyl 7.3L 446"
1993-1998	Ford	Bronco, F Series	8 Cyl 7.5L 460"
1993-1998	Ford	Ranger	4 Cyl 2.3L 140"
1993-1998	Ford	Ranger	6 Cyl 3.0L 183"
1993-1998	Ford	Ranger	6 Cyl 4.0L 244"
1993-1998	Ford	Explorer	6 Cyl 4.0L 244"
1994-1998	Mazda	B2300	4 Cyl 2.3L 140"
1994-1998	Mazda	B3000	6 Cyl 3.0L 183"
1994-1998	Mazda	B4000	6 Cyl 4.0L 244"
1993-1994	Mazda	Navajo	6 Cyl 4.0L 244"

****For additional information, refer to Ford bulletin #97-22-17.***