



# Technical Service Bulletin

## Squeaking Noise

Referenced applications may produce a squeaking noise while the clutch pedal is actuated or released. The noise also may be detectable with the engine off while cycling the clutch pedal.



**PDL CSC SC0723**

If you confirm the noise is coming from the bell housing, replace the slave cylinder with Platinum Driveline item number SC0723 or revised Ford part #6L5Z-7A508-AA.

### **Affected Applications:**

Year	Make	Model	Engine
2004-06	Ford	Ranger	4 cyl 2.3L 140"
2004-06	Ford	Ranger	4 cyl 3.0L 183"
2004-06	Ford	Ranger	4 cyl 4.0L 244"

***\*For additional information, refer to Ford bulletin #06-23-13.***