



Technical Service Bulletin

Due to a supplier discontinuation of the interlock switch, Platinum Driveline will start shipping the prefilled clutch assemblies listed below, without the switch assembly content. We are in the process of reviewing other supplier options but as of today, there is no immediate solution.

Here is an example of a Prefilled System and the switch assembly:



Affected Applications

PDL Item		
PMC0433	PSC0119	PSC0520
PMC0434	PSC0119-2	PSC0523
PMC0445	PSC0119-3	PSC0523-2
PMC0486	PSC0119-4	PSC0523-2HD
PMC0486-1	PSC0119-5	PSC0523-3
PMC0486-2	PSC0119-6	PSC0560
PMC0581	PSC0120	PSC0572
PMC0703-2	PSC0120-2	PSC0588
PMC0706	PSC0120-3	PSC0589
PMC0710-2	PSC0419	PSC0592
PMC0716	PSC0425	PSC0592-1
PMC0717	PSC0427	PSC0593
PMC0718	PSC0433	PSC0713
PMC0718-2	PSC0435	PSC0714
PMC0719	PSC0437	PSC0721
PMC0720	PSC0482	PSC0721-2
PMC0720-2	PSC0482-2	PSC0722
PMC0724	PSC0485	PSC0726
PMC0726	PSC0516	PSC0727
PSC0112-2	PSC0517	PSC0738
PSC0114	PSC0517-2	PSC0790
	PSC0517-3	

This change will go into effect immediately.