



## Technical Service Bulletin

A 12-inch clutch upgrade, recommended for all non-turbos and vehicles equipped with aftermarket turbochargers.



**PDL: 07-100**

The upgrade replaces the original 11-inch clutch. When installing the clutch, ensure the correct Dual-Mass flywheel is installed.

Flywheels on different applications are balanced differently and interchanging them may result in vibration and driveline damage.

### **Affected Items:**

Year	Make	Model	Engine	Kit
1988-1994	Ford	F-250, F-350	7.3L Non-Turbo	07-100
1988-1994	Ford	F-450	7.3L Non-Turbo	07-100

*\*Always install new flywheel-crankshaft bolts and torque them to 45-49 ft-lb.*

*\*PDL does not carry DMF or matching crank bolts*