



## Technical Service Bulletin

For some Dodge 3.9L Truck applications, excessive flywheel machining and installation of the wrong mounting bolts can damage the crankshaft position sensor.



***Crank Position Sensor 56026701***

The sensor is mounted on the block directly behind the bolt circle of the clutch mounting bolts. Ensure the correct mounting bolts are installed and a minimum amount of material is machined off the flywheel.

### **Affected Items:**

Year	Make	Engine	Kit
1988-1991	Dodge Truck	V6 3.9L 240"	05-031
1992-1993	Dodge Truck	V6 3.9L 240"	05-038
1992-1993	Dodge Truck	V6 3.9L 240"	05-063