



Technical Service Bulletin

For the following applications, where a clutch release shaft is used, the roll pins securing the release fork to the cross shaft can fatigue and break. This enables the fork to turn on the shaft causing a no release issue. Replace the pins and ensure they fit snugly in the holes.



Mitsubishi Release Shaft MD719242



Hyundai Release Shaft 41430-22610

Affected Items:

Year	Make	Model	Engine
1989-1990	Dodge	2000 GTX	4 Cyl 2.0L 1997cc
1985-1994	Dodge	Colt 1500	4 Cyl 1.5L 1500cc
1985-1988	Dodge	Colt 1600	4 Cyl 1.6L 1597cc
1984-1987	Dodge	Colt Vista	4 Cyl 2.0L 1997cc
1989-1994	Eagle	Summit	4 Cyl 1.5L 1468cc
1989-1990	Eagle	Summit	4 Cyl 1.6L 1597cc
1989-1994	Eagle	Talon	4 Cyl 1.8L 1755cc
1992-1993	Hyundai	Elantra	4 Cyl 1.6L 1599cc
1986-1994	Hyundai	Excel	4 Cyl 1.5L 1500cc
1991-1995	Hyundai	Scoupe	4 Cyl 1.5L 1500cc
1982-1988	Mitsubishi	Cordia	4 Cyl 1.8L 1795cc
1984-1988	Mitsubishi	Cordia	4 Cyl 2.0L 1997cc
1990-1994	Mitsubishi	Eclipse	4 Cyl 1.8L 1755cc
1985-1994	Mitsubishi	Mirage	4 Cyl 1.5L 1468cc
1985-1992	Mitsubishi	Mirage	4 Cyl 1.6L 1597cc
1987-1993	Mitsubishi	Precis	4 Cyl 1.5L 1468cc
1983-1988	Mitsubishi	Tredia	4 Cyl 1.8L 1795cc
1984-1988	Mitsubishi	Tredia	4 Cyl 2.0L 1997cc
1985-1994	Plymouth	Colt 1500	4 Cyl 1.5L 1500cc
1985-1988	Plymouth	Colt 1600	4 Cyl 1.6L 1600cc
1984-1987	Plymouth	Colt Vista	4 Cyl 2.0L 2000cc
1989-1994	Plymouth	Laser	4 Cyl 1.8L 1755cc

**** Replace the fork if necessary.***