



## Technical Service Bulletin

### GM Concentric Slave Cylinder Missing Pipe Clips

This bulletin is explaining some changes to SC0425WL. The white clips shown in the picture below are no longer available:

The CSC will be shipped without the white clips. The clips are used to route the pipe. If they are not used, the pipe could come in contact with a heat source or moving part.

**\*It is very important that the pipe is routed properly.\***

The end user will have to reuse the original clips. Keep the white clips mounted to the body and remove the pipe from the clips. Install the new system, and attach the new hose into the old clips. The white clips will hold the clutch hose and another routing. The end user will have to ensure both objects are retained by the white clips and not rubbing against anything.

