

Subaru Repair Sleeve

The OE release bearing retainer, in some Subaru models, is subject to failure and can only be repaired by replacing the transmission case. In these applications, the bearing retainer is built into the transmission case and requires costly repair procedures.

Affected Applications

Years	Application	Item
2006-2006	Saab 9-2X 4 Cyl 2.5L 2458cc	15-026 / 15-030
2006-2006	Subaru Baja 4 Cyl 2.5L 2458cc	15-026 / 15-030
2006-2008	Subaru Forester 4 Cyl 2.5L 2458cc	15-026 / 15-030
2007-2011	Subaru Forester 4 Cyl 2.5L 2458cc	15-026 / 15-030
2006-2006	Subaru Impreza, Impreza WRX 4 Cyl 2.5L 2458cc	15-030
2008-2013	Subaru Impreza, Impreza WRX 4 Cyl 2.5L 2458cc	15-030
2014-2014	Subaru Impreza, Impreza WRX 4 Cyl 2.5L 2458cc	15-030
2015-2018	Subaru Impreza, Impreza WRX 4 Cyl 2.0L 1994cc	15-026
2005-2006	Subaru Legacy, Legacy Wagon, Legacy Outback 4 Cyl 2.5L 2458cc	15-026 / 15-030
2005-2006	Subaru Legacy, Legacy Wagon, Legacy Outback 4 Cyl 2.5L 2458cc	15-027
2007-2009	Subaru Legacy, Legacy Wagon, Legacy Outback 4 Cyl 2.5L 2458cc	15-026 / 15-030
2010-2012	Subaru Legacy, Legacy Wagon, Legacy Outback 4 Cyl 2.5L 2458cc	15-026 / 15-030
2005-2006	Subaru Outback 4 Cyl 2.5L 2458cc	15-026 / 15-030
2005-2006	Subaru Outback 4 Cyl 2.5L 2458cc	15-027
2007-2008	Subaru Outback 4 Cyl 2.5L 2458cc	15-026 / 15-030
2013-2014	Subaru WRX, WRX STI 4 Cyl 2.5L 2458cc	15-026 / 15-030
2015-2017	Subaru WRX, WRX STI 4 Cyl 2.0L 1998cc	15-026 / 15-030
2018-2020	Subaru WRX, WRX STI 4 Cyl 2.0L 1998cc	15-033



N844SAR (Included in the above kits)

The release bearing with repair sleeve offered in our kits is an inexpensive, and easy to install alternative to the case replacement.