



## N3743 Audi/VW Slave Cylinder

On Audi and Volkswagen models, slave cylinder N3743 is **NOT** designed to be pre-bled (bench bled) or compressed before installation.

### **Affected Applications**

Year	Make	Model	Clutch Kits
2006-2013	Audi	A3	02-017, 02-117, 17-068
2000-2002	Audi	TT	02-017, 02-117
2000-2009	Audi	TT Quattro	02-017, 02-038, 02-057, 02-117
2002-2005	Volkswagen	Beetle	02-017, 02-117
2009-2011	Volkswagen	CC	17-068
2007-2011	Volkswagen	Eos	17-067, 17-068
2002-2011	Volkswagen	Golf	02-017, 02-057, 02-117 17-067, 17-068
2009-2010	Volkswagen	Golf City	02-017, 02-117
2003-2011	Volkswagen	Jetta	02-017, 02-057, 02-117 17-067, 17-068
2006-2010	Volkswagen	Passat	02-056, 17-067, 17-068

If the slave cylinder is pre-bled and/or compressed, it is likely that the seal will become misaligned and leak therefore causing the cylinder to fail upon installation. The slave cylinder is **ONLY** designed to function properly after it is installed in the bell housing.

