

Subaru Repair Sleeve


The OE release bearing retainer, in some Subaru models, is subject to failure and can only be repaired by replacing the transmission case. In these applications, the bearing retainer is built into the transmission case and requires costly repair procedures.

Affected Applications

Years	Application	Item
1990-1995	Subaru Legacy, Legacy Wagon, Legacy Outback 4cyl 2.2L 2212cc	15-010
1993-1993	Subaru Impreza, Impreza WRX 4cyl 1.8L 1781cc 4-Wheel Drive	15-012
1994-1997	Subaru Impreza, Impreza WRX 4cyl 1.8L 1781cc	15-010
1995-1995	Subaru Impreza, Impreza WRX 4cyl 1.8L 1781cc 2-Wheel Drive	15-018
1995-2001	Subaru Impreza, Impreza WRX 4cyl 2.2L 2212cc	15-010
1996-2009	Subaru Legacy, Legacy Wagon, Legacy Outback 4cyl 2.5L 2458cc	15-004
1998-2004	Subaru Impreza, Impreza WRX 4cyl 2.5L 2458cc Ej25D,Ej251, Ej253	15-004
1998-2012	Subaru Forester 4cyl 2.5L 2458cc Non-Turbo	15-004
2000-2011	Subaru Outback 4cyl 2.5L 2458cc	15-004
2001-2004	Subaru Outback 6cyl 3.0L	15-004
2003-2005	Subaru Baja 4cyl 2.5L 2458cc Exc.Turbo	15-004
2004-2006	Subaru Impreza, Impreza WRX H4 2.5L 2458Cc	15-007
2005-2006	Saab 9-2X 4cyl 2.5L 2458cc Non-Turbo	15-004
2007-2007	Subaru Impreza, Impreza WRX H4 2.5L 2458Cc	15-007
2007-2011	Subaru Impreza, Impreza WRX 4cyl 2.5L 2458cc Ej253	15-004
2008-2012	Subaru Impreza, Impreza WRX H4 2.5L 2458Cc	15-007
2010-2012	Subaru Legacy, Legacy Wagon, Legacy Outback H4 2.5L 2458Cc	15-029
2010-2013	Subaru Impreza, Impreza WRX 4cyl 2.0L 1994cc	15-004

Affected Applications Contd.

Years	Application	Item
2010-2018	Subaru Outback H4 2.5L 2458Cc	15-029
2011-2014	Subaru Forester 4cyl 2.5L 2498cc	15-004
2013-2014	Subaru Impreza, Impreza WRX H4 2.5L 2458Cc	15-007
2013-2015	Subaru Xv Crosstrek H4 2L 1999Cc	15-007
2013-2016	Subaru Impreza, Impreza WRX H4 2L 1994Cc	15-007
2013-2016	Scion Fr-S 4cyl 2.0L 1998cc	15-020
2013-2016	Subaru BRZ 4cyl 2.0L 1998cc	15-020
2013-2017	Subaru Outback H4 2.5L 2498Cc	15-029
2014-2016	Subaru Forester H4 2.5L 2458Cc	15-029
2016-2017	Subaru Xv Crosstrek H4 2L 1999Cc	15-007
2016-2017	Subaru Crosstrek 4cyl 2.0L 1995cc 5-Speed	15-004
2016-2018	Subaru Forester H4 2.5L 2498Cc	15-029
2017-2020	Toyota 86 4cyl 2.0L 1998cc	15-020
2018-2020	Subaru Crosstrek H4 2L 1995Cc	15-029



N051SAR (Included in the above kits)

The release bearing with repair sleeve offered in our kits is an inexpensive, and easy to install alternative to the case replacement.