




Technical Service Bulletin

Do Not Lubricate!

The release bearing and pre-lubricated internal slave cylinder are designed to operate without any additional lubrication. Do not lubricate these parts during installation. Doing so may cause premature failure.



Affected Applications:

Year	Make	Model	Engine
1993-03	Ford	Explorer	6 cyl 4.0L 244"
1995-11	Ford	Ranger	4 cyl 2.3L 140"
1998-01	Ford	Ranger	4 cyl 2.5L 150"
1995-08	Ford	Ranger	6 cyl 3.0L 183"
1993-11	Ford	Ranger	6 cyl 4.0L 244"
1995-10	Mazda	B2300	4 cyl 2.3L 2295cc
1998-01	Mazda	B2500	4 cyl 2.5L 2500cc
1995-08	Mazda	B3000	6 cyl 3.0L 3000cc
1994-09	Mazda	B4000	6 cyl 4.0L 4000cc
1992-94	Mazda	Navajo	6 cyl 4.0L 4000cc