



CSC Product Information

Platinum Driveline offers a line of Concentric Slave Cylinders (CSC) with or without the bearing. Some CSCs come with a replaceable bearing which can make repairs more cost effective and less time-consuming.



CSC without Bearing



CSC with Bearing

The thrust face of the bearing is in constant contact with the pressure plate diaphragm, which sometimes causes the bearing to fail prior to the slave cylinder. If the hydraulic system is thoroughly and properly checked, and no faults are discovered, replacement of the bearing alone may be sufficient.

If the hydraulic system is leaking, or not releasing, then replacement of the CSC is **necessary**.

PDL Item*	Bearing to Pair with NB
SC0418	N1764SA
SC0419	N1764SA
SC0421	N1775SA
SC0422	N1775SA
SC0423	N1775SA
SC0466	N1786SA
SC0482	N1764SA
SC0536	N1754SA
SC0579	N1775SA
SC0706	N1738SA
SC0707	N1754SA
SC0710	N1763SA
SC0723	N1775SA

*For part numbers without the bearing, add the suffix "NB" (SC0418NB)